CIVIL QUALITY CONSULTANTS & ENGINEERS

ISO 9001:2015 Certified & NABL Accredited Laboratory as per ISO/IEC - 17025-2017

Testing of Construction Material - Mechanical, Soil, Bitumen, Non Destructive Testing Services, Project Management Consultants, Third Party Quality Assurance, DPR.

Name of Work : Improvements and Development of school building at Jalahalli in ward No.16, BBMP, Bangalore.

Name of Client	:	**Executive Engineer,** RR Nagara Division, BBMP, Bangalore.
Contractor/Agency	:	**Sri. K Damodar & Co,** Contractor, Bangalore.
Total Cost	:	Rs. 117.22 Lakhs
Date of Inspection	:	07.01.2022
Status of Bill	:	1st and Part Bill
Work Order No.	:	EE/RRND/Wo.No/000060/2021-22
In the Presence of	:	(a) **Assistant Engineer (W. No.16),** BBMP, Bangalore.
	:	(b) **Mr. Mohan G,** Engineer M/S Civil Quality Consultants and Engineers, Bangalore

Sl.No	Description of the Item		Quantity	Unit	Comments / observations
1	KSRRB M200-12.1. Dismantling of existing structures like culverts,		181.7	Cum	Work done up to the billed quantity and Quality is satisfactory
2	KSRRB M200-14.1. Dismantling of existing	:	197.34	Cum	Work done up to the billed quantity and Quality is satisfactory
3	KSRB 200-7.1 : Clearing grass and removal of rubbish	:	0.15	HA	Work done up to the billed quantity and Quality is satisfactory
4	KSRB 2-2.1 Earth work excavation for foundation of	:	974.4	Cum	Work done up to the billed quantity and Quality is satisfactory
5	KSRB-3.2 : Providing and injecting chemical emulsion	:	997.88	Sqm	Work done up to the billed quantity and Quality is satisfactory
6	Providing and filling in foundation / below flooring	:	131.51	Cum	Work done up to the billed quantity and Quality is satisfactory
7	KSRB 4-1.2 Providing and Laying in position plain	:	119.55	Cum	Work done up to the billed quantity and Quality is satisfactory

For CIVIL QUALITY CONSULTANTS & ENGINEERS

Authorised Signatory

Corporate Off.: No. 133, Bhuvaneshwarinagar, Doddabasti Main Road, Bangalore-560 056.
Contact: 8553518550, 080-23240644 Email: civilqualityconsultants@gmail.com

Scanned with CamScanner

Sl.No	Description of the Item		Quantity	Unit	Comments / observations
8	KSRB 4.9.2: Providing T.M.T steel reinforcement	:	56.46	Sqm	Work done up to the billed quantity and Quality is satisfactory
9	KSRB 4-6.1 : Providing and removing a centering,	:	22.12	Cum	Work done up to the billed quantity and Quality is satisfactory
10	KSRB 4.2.7 : Providing and laying in position reinforced	:	21.2	Cum	Work done up to the billed quantity and Quality is satisfactory
11	KSRB 4-6.5: Providing and removing centering,	:	251.94	Sqm	Work done up to the billed quantity and Quality is satisfactory
12	KSRB 4.2.7 : Providing and laying in position reinforced	:	231.27	Sqm	Work done up to the billed quantity and Quality is satisfactory
13	KSRB 4.6.4: Providing and removing centring,	:	32.22	Cum	Work done up to the billed quantity and Quality is satisfactory
14	KSRB 4.2.7 : Providing and laying in position reinforced	:	320.65	Sqm	Work done up to the billed quantity and Quality is satisfactory
15	ksrb 5.2-3 Providing and constructing grinite	:	92.08	Cum	Work done up to the billed quantity and Quality is satisfactory
16	KSRB 5.3-3 : Providing and constructing granite / trap /	:	86.23	Cum	Work done up to the billed quantity and Quality is satisfactory
17	KSRB-15.2.2 Providing ruled pointing to coursed	:	51.98	Sqm	Work done up to the billed quantity and Quality is satisfactory
18	KSRB 2.3 : Filling available excavated earth (excluded	:	1060.94	Cum	Work done up to the billed quantity and Quality is satisfactory
19	KSRB 4-6.3: Providing and removing centering,	:	664.57	Sqm	Work done up to the billed quantity and Quality is satisfactory
20	KSRB 4-6.7: Providing and removing centering,	:	691.67	Sqm	Work done up to the billed quantity and Quality is satisfactory
21	KSRB 4.9.2: Providing T.M.T steel reinforcement	:	56.46	Sqm	Work done up to the billed quantity and Quality is satisfactory
22	Providing and laying cement concrete using 20mm down	:	314.5	Sqm	Work done up to the billed quantity and Quality is satisfactory
23	Providing and laying cement concrete using 20mm down	:	138.43	Nos	Work done up to the billed quantity and Quality is satisfactory
24	KSRB 5-14.1 : Providing and constructing percast	:	137.11	Cum	Work done up to the billed quantity and Quality is satisfactory

For CIVIL QUALITY CONSULTANTS & ENGINEERS

Corporate Off.: No. 133, Bhuvaneshwarinagar, Doddabasti Main Road, Bangalore-560 056.
Contact: 8553518550, 080-23240644 Email: civilqualityconsultants@gmail.com

Authorised Signatory

Scanned with CamScanner

CIVIL QUALITY
CONSULTANTS & ENGINEERS
ISO 9001:2015 Certified & NABL Accredited
Laboratory as per ISO/IEC - 17025-2017

Testing of Construction Material - Mechanical, Soil, Bitumen, Non Destructive Testing Services, Project Management Consultants, Third Party Quality Assurance, DPR.

Sl.No	Description of the Item		Quantity	Unit	Comments / observations
25	Geophysical investigation of site for Sinking borewell for	:	667.08	Sqm	Work done up to the billed quantity and Quality is satisfactory
26	Sinking borewell of 165 mm dia clear using super fast	:	667.52	Sqm	Work done up to the billed quantity and Quality is satisfactory
27	Geophysical investigation of site for Sinking borewell for	:	65.56	Tonn	Work done up to the billed quantity and Quality is satisfactory
28	Geophysical investigation of site for Sinking borewell for	:	70.93	Cum	Work done up to the billed quantity and Quality is satisfactory
29	Geophysical investigation of site for Sinking borewell for	:	1	No's	Work done up to the billed quantity and Quality is satisfactory
30	Geophysical investigation of site for Sinking borewell for	:	50	Sqm	Work done up to the billed quantity and Quality is satisfactory
31	Geophysical investigation of site for Sinking borewell for	:	50	Rmt	Work done up to the billed quantity and Quality is satisfactory
32	Geophysical investigation of site for Sinking borewell for	:	50	Rmt	Work done up to the billed quantity and Quality is satisfactory
33	Geophysical investigation of site for Sinking borewell for	:	50	Rmt	Work done up to the billed quantity and Quality is satisfactory
34	Geophysical investigation of site for Sinking borewell for	:	50	Rmt	Work done up to the billed quantity and Quality is satisfactory
35	Geophysical investigation of site for Sinking borewell for	:	50	Rmt	Work done up to the billed quantity and Quality is satisfactory
36	Geophysical investigation of site for Sinking borewell for	:	20	Rmt	Work done up to the billed quantity and Quality is satisfactory
37	Providing and fixing 250mm dia PVC (casing pipe) (page	:	12	Rmt	Work done up to the billed quantity and Quality is satisfactory
38	Supply of ISI Mark 175mm nominal Bore, Plain end	:	50	Rmt	Work done up to the billed quantity and Quality is satisfactory
39	Providing 175mm Dia M.S. Collar (P.No.iii,I.No.86)	:	8	No's	Work done up to the billed quantity and Quality is satisfactory
40	Providing 175mm dia Bore Cap CE (M)	:	1	No's	Work done up to the billed quantity and Quality is satisfactory
41	Atalanta suguna CRI KIRLOSKAR and other	:	1	No's	Work done up to the billed quantity and Quality is satisfactory

For CIVIL QUALITY CONSULTANTS & ENGINEERS

Corporate Off.: No. 133, Bhuvaneshwarinagar, Doddabasti Main Road, Bangalore-560 056.
Contact: 8553518550, 080-23240644 Email: civilqualityconsultants@gmail.com

Authorised Signatory

Scanned with CamScanner

CIVIL QUALITY CONSULTANTS & ENGINEERS
ISO 9001:2015 Certified & NABL Accredited Laboratory as per ISO/IEC - 17025-2017
Testing of Construction Material - Mechanical, Soil, Bitumen, Non Destructive Testing Services, Project Management Consultants, Third Party Quality Assurance, DPR.

Sl.No	Description of the Item		Quantity	Unit	Comments / observations
42	Providing and fixing in trenches galvinised/mild	:	370	Rmt	Work done up to the billed quantity and Quality is satisfactory
43	Supplying and drawing 3 core flat PVC sheathed	:	750	Rmt	Work done up to the billed quantity and Quality is satisfactory
44	Providing and fixing in position 50mm Nominal	:	1	No's	Work done up to the billed quantity and Quality is satisfactory
45	Spplying and fixing 50mm GI Union.(PWD SR 2018-	:	1	No's	Work done up to the billed quantity and Quality is satisfactory
46	Spplying and fixing 50mm GI Elbow.(PWD SR 2018-	:	1	No's	Work done up to the billed quantity and Quality is satisfactory
47	Spplying and fixing 50mm GI Nipple.(PWD SR 2018-	:	1	No's	Work done up to the billed quantity and Quality is satisfactory
48	Spplying and fixing 50mm GI Hose colleres(PWD SR 2018-19,P-XXXIX)	:	62	No's	Work done up to the billed quantity and Quality is satisfactory
49	Supplying and fixing 20" x 20" x 2.5" polished wood	:	1	No's	Work done up to the billed quantity and Quality is satisfactory
50	Supplying and fixing miniature circuit breakers on	:	1	No's	Work done up to the billed quantity and Quality is satisfactory
51	Supplying of TPST with rewirable porcelain channels	:	1	No's	Work done up to the billed quantity and Quality is satisfactory
52	Supplying and fixing LED type panel board indicating	:	1	No's	Work done up to the billed quantity and Quality is satisfactory
53	Suppling fully automatic star delta starter unit push button	:	1	No's	Work done up to the billed quantity and Quality is satisfactory
54	Supplying and fixing single phase preventer using	:	1	No's	Work done up to the billed quantity and Quality is satisfactory
55	Wiring for lighting/power circuit using one of FRLS	:	20	Mtrs	Work done up to the billed quantity and Quality is satisfactory
56	Supplying fixing and wiring heavy duty low voltage	:	4	No's	Work done up to the billed quantity and Quality is satisfactory
57	Supplying, fixing, wiring, earth electrode for	:	1	No's	Work done up to the billed quantity and Quality is satisfactory

For CIVIL QUALITY CONSULTANTS & ENGINEERS

Corporate Off.: No. 133, Bhuvaneshwarinagar, Doddabasti Main Road, Bangalore-560 056.
Contact: 8553518550, 080-23240644 Email: civilqualityconsultants@gmail.com

Authorised Signatory

Scanned with CamScanner

Sl.No	Description of the Item		Quantity	Unit	Comments / observations
58	Digging of trench of 0.36mtrs deepx0.5 mtrs wide	:	8	Mtrs	Work done up to the billed quantity and Quality is satisfactory
59	Supplying laying 1.1 KV class LT UG cable having	:	10	Mtrs	Work done up to the billed quantity and Quality is satisfactory
60	Labour charge for laying 1.1 KV class UG cable in	:	25	No's	Work done up to the billed quantity and Quality is satisfactory
61	Supplying and fixing class-A(medium duty) GI pipe	:	2	Rmt	Work done up to the billed quantity and Quality is satisfactory
62	Supplying and fixing LT cast iron pot heads suitable for	:	1	No's	Work done up to the billed quantity and Quality is satisfactory
63	Supplying and fixing porcelain fuse channel with	:	3	No's	Work done up to the billed quantity and Quality is satisfactory
64	KSRB 4.9.2: Providing T.M.T steel reinforcement	:	49.95	Sqm	Work done up to the billed quantity and Quality is satisfactory
65	KSRB 4-6.5: Providing and removing centering,	:	118.3	Mtrs	Work done up to the billed quantity and Quality is satisfactory
66	KSRB 4.2.7 : Providing and laying in position reinforced	:	828.29	Mtrs	Work done up to the billed quantity and Quality is satisfactory
67	KSRB 4-6.3: Providing and removing centering,	:	36	No's	Work done up to the billed quantity and Quality is satisfactory

For CIVIL QUALITY CONSULTANTS & ENGINEERS

Authorised Signatory

Scanned with CamScanner